

Moulin ak rach

- Toujou met pwoteksyon nan zòrey, zye ak figi w
- Eten machin nan anvan w retire materyèl ki kole ladan oubyen pou w range l. Rale pedal la pou anpeche moun opere machin nan, locke control la epi retire kle a ladan.
- Met baryè nan espas kote ekipman you ye pou anpeche lòt moun antre
- Pa janm mete ti moso bwa kout ak men w. Sa ka tiye w oubyen koupe yon manb ou.

Zenith provides workplace safety resources at: **TheZenith.com**[®]